

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4 6 0 3	DATE	November. 7. 2019
MANUFACTURER	TRANTECHS. CO. , LTD		
DESCRIPTION OF DEFECT	In horizontal suspension spare tire carriers for medium trucks, the shape of the hanging plate is inappropriate, when a tire with an aluminum wheel is fixed to the carrier, spare tires may rotate due to vibration while moving. For that reason, the spare tire carrier chain and suspension plate can scrape together potentially causing the spare tire carrier chain to break and in the worst-case scenario, the spare tires may fall off.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FRR90S2	FORWARD	2018~2019	32
2PG-FRR90T2			
2RG-FRR90S2			
2RG-FRR90T2			
		TOTAL	32