

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	4614	DATE	November 12 ,2019
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	Regarding the rear combination lamp for semi-trailer, the mounting position of the lamp does not comply with Article 41 of the safety standard (standard of direction indicator) due to the setting of the mounting position is inappropriate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PLB24101	—	2019	10
		TOTAL	10