

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4606	DATE	Nov.14 2019
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty trucks, the DPF muffler mounting bracket interferes with the fuel piping because the setting of the mounting bracket is inappropriate. For this reason, the fuel piping can be damaged due to vibration during traveling resulting in a fuel leak. In the worst case, a fire will occur.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2PG-FEAV0	「FUSO CANTER」	2019~2019	4
		TOTAL	4