

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2951	DATE	2019/11/21
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain C-Class, E-Class and E-Class Coupe vehicles (205, 213, 238 platforms) with rear-wheel drive a locknut in the steering rack might exhibit cracks. In the very improbable case that a pre-damaged locknut was installed in a vehicle, this locknut might break due to exposure of the steering to very high lateral forces, which can occur for example in case of contact with the curb during maneuvering or parking. In consequence, rotating components inside the steering rack might contact the housing, leading to a blocking of the steering. In this case, the risk of a crash is increased.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-205040C	C180	2015	1
		2016	1
		2018	724
		2019	101
RBA-205042	C200	2015	2
		2016	1
		2018	141
RBA-205042C	C200	2015	5
		2018	68
DAA-205077	C200	2019	312
DAA-205077C			54
LDA-205004	C220d	2018	381
LDA-205014		2019	116
LDA-205014C			17
DLA-205047	C350e	2018	16
DBA-205240C	C180 Stationwagon	2016	1
		2018	285
		2019	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RBA-205242	C200 Stationwagon	2015	2
RBA-205242C		2018	87
LDA-205204	C220d Stationwagon		24
DBA-205340C	C180 Coupe		183
DBA-205440C	C180 Cabriolet		38
RBA-213042C	E200	2018	1
LDA-213004C	E220d		25
RBA-213045C	E250	2017	156
DLA-213050C	E350e	2018	144
RBA-213242C	E200 Stationwagon	2017	1
LDA-213204C	E220d Stationwagon	2018	62
RBA-213245C	E250 Stationwagon		168
RBA-238342C	E200 Coupe		30
DBA-238348C	E300 Coupe		83
RBA-238442C	E200 Cabriolet		25
CBA-205087	Mercedes AMG C63S		2015
CBA-205287		Mercedes AMG C63S Stationwagon	2018
CBA-205387	Mercedes AMG C63S Coupe	2018	1
CBA-205487	Mercedes AMG C63S Cabriolet		2
		TOTAL	3,432