

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2952	DATE	2019/11/21
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On certain CLS vehicles (257 platform) with 6-cylinder gasoline engine M256 the electric line for the power supply of the engine coolant pump might contact the engine fan and chafe on it.</p> <p>Due to chafing on the engine fan, the electric line could be damaged, potentially leading to a malfunction of the engine coolant pump or a deactivation of the 48V on-board electrical system.</p> <p>If the engine coolant pump malfunctions, the engine coolant temperature could increase, potentially leading to an engine stall.</p> <p>If the 48V on-board electrical system becomes deactivated while the engine is running, the vehicle could be continued to be driven. However, a restart of the engine would not be possible after it was switched off by the ECO start/stop function or the glide mode.</p> <p>In both cases, the vehicle propulsion would be lost, increasing the risk of a crash.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DAA-257359	CLS450 4MATIC	2019	1666
		TOTAL	1666