

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~(~~ Import Vehicles)

CAMPAIGN No.	Gai-2957	DATE	2019/11/21
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On certain SL-Class vehicles (231 platform) the passenger airbag cushion may not have been sewn according to manufacturing specification. In of the event of a deployment, the passenger airbag cushion might rip open at the circumferential seam. As a result, the restraint function of the passenger airbag might be impaired, increasing the risk of injury for the passenger.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-231466	SL400	2018	7
		2019	23
CBA-231473	SL550	2019	5
CBA-231474	SL63	2019	5
		TOTAL	40