

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4619	DATE	Nov.27.2019
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	On intake valves, due to an improper assemble operation, there is a possibility that the wrong intake valves were installed. If this were to occur, the intake valves will contact with the cylinder bore and/or pistons, and in the worst case, the engine will be broken.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
6BA-MXAA54	[RAV4]	2019	2
		TOTAL	2