

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2963	DATE	November 27 th , 2019
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate process control, a spherical-collar disk may not have been fitted on the track rod end during supplier's production. This could lead to an excessive wear of the track rod end. Thus, the track rod can break over the service life. Breakage of the track rod could lead to the loss of steering control.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-WJ20M	MINI Cooper S Convertible	2019	1
LDA-YT20	MINI Cooper D Crossover	2019	1
		TOTAL	2