

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4611	DATE	Nov. 28, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to an improper combination of the rear suspension coil spring steel material and its coating specification, if the coating film is damaged from foreign materials such as stones being caught between the lower part of the coil spring and the coil spring seat area of the shock absorber, the coil spring may corrode. As the corroding escalates, in the worst case, coil spring may fracture.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-SJ5	「Forester」	2013 ~ 2015	49,162
DBA-SJG		2013 ~ 2015	17,446
		TOTAL	66,608