

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	4612	DATE	Nov.28, 2019
MANUFACTURER	SUBARU CORPORATION		
DESCRIPTION OF DEFECT	Due to an improper material used for Positive Crankcase Ventilation valve, which is a part of blow-by gas ventilation system, the crankcase may lack its durability for certain vehicles. If the connection part fractures, engine oil may flow into combustion chamber and burn, exceeding amount of smoke may be released from muffler, and in the worst case, engine may stall while driving.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
5AA-GTE	「XV」	2018	516
5AA-SKE	「Forester」	2018	4,041
5BA-SK9		2018	9,876
		TOTAL	14,433