

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	4618	DATE	November 28. 2019
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	In the hydrostatic transmission of agricultural combine harvester, waterproof structure of HST lever is inappropriate, some rust is generated when water enters the sliding part of the HST lever. Therefore, the sliding resistance of the lever increases, and in the worst case, even if the main transmission lever is operated to the neutral position, the HST lever does not return to the neutral position, and driving may not stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「YH440」	2015~2019	729
-	「YH448」	2015~2019	1,668
TOTAL			2,397