

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai – 2939	DATE	29 November, 2019
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that an airbag control unit with a faulty capacitor for the power supply has been installed in the affected vehicles. This faulty capacitor in the airbag control unit can lead to an unexpected deployment or non-deployment of the airbags and/or safety belt pretensioners.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-970CWA	Panamera	2016	92
	Panamera 4	2016	16
ABA-970CWAA	Panamera	2016	7
	Panamera 4	2016	1
ABA-970CWBA	Panamera Turbo	2016	3
ABA-970CWDA	Panamera S	2016	2
	Panamera 4S	2016	2
ABA-970CWDAX	Panamera 4S	2016	1
ABA-970CXPA	Panamera GTS	2016	23
ABA-970CGEA	Panamera S e-hybrid	2016	21
ABA-991MA103	911 Carrera S	2016	24
	911 Carrera 4S	2016	20
	911 Carrera GTS	2016	13
	911 Targa 4S	2016	4
	911 Targa 4 GTS	2016	8
ABA-991MA104	911 Carrera	2016	98
	911 Carrera 4	2016	46
	911 Targa 4	2016	5
ABA-991MA171	911 Turbo	2016	23
	911 Turbo S	2016	47

ABA-MA175	911 GT3	2016	1
-991MA175-	911 GT3RS	2016	46
ABA-991H1	911 Carrera	2017	38
	911 Carrera 4	2017	4
	911 Carrera S	2017	45
	911 Carrera 4S	2017	7
	911 Targa 4S	2017	1
ABA-981MA122	Boxster	2016	144
	Cayman	2016	61
ABA-981MA123	Boxster S	2016	8
	Boxster GTS	2016	56
	Cayman S	2016	46
	Cayman GTS	2016	76
ABA-981DBX	Boxster Spyder	2016	24
	Cayman GT4	2016	131
		TOTAL	1222