

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	Gai-2965	DATE	Dec. 6, 2019
MANUFACTURE	Harley-Davidson Motor Company (Japanese Importer : Harley-Davidson Japan K.K. )		
DESCRIPTION OF DEFECT	The electro-hydraulic control unit (EHCU) software on affected motorcycles may respond incorrectly to a faulty rear wheel speed signal by activating one of the rear brakes. Unintended activation of one rear brake could lead to an unexpected change in vehicle direction which may increase the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2BL-TGF	TRI GLIDE ULTRA	2019 - 2020	400
2BL-TGP	FREEWHEELER	2019 - 2020	59
TBH	CVO TRI GRIDE	2020	39
		TOTAL	498