

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2940	Date	Dec 12, 2019
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On airbag CU, durability of capacitor for power supply is insufficient in some production due to improper curing process of capacitor for power supply. As a result, when a capacitor deteriorate, a malfunction occur in a control unit. In the worst case, airbag and seat belt tensioner might suddenly operate or not operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-7NCTH	VW Sharan 1.4 110kW	MY2015	44
DBA-7NCZD		MY2016	1,441
ABA-5NCCZ	VW Tiguan 2.0T	MY2015-MY2016	81
DBA-5NCTH	VW Tiguan 1.4	MY2015-MY2016	436
ABA-3CCDAC	VW CC 1.8T	MY2015-MY2016	9
		Total	2,011