

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

| | | | |
|-----------------------|--|------|-------------------|
| CAMPAIGN No. | 4630 | DATE | December 17, 2019 |
| MANUFACTURE | SUMITOMO NACCO FORKLIFT CO., LTD. (Japan) | | |
| DESCRIPTION OF DEFECT | When replacing the LPG tank, the packing may come off from the LPG stop valve. Therefore, the fuel cannot be sealed in the tank and may leak to the outside. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|-----------|-------------------------------------|---------------------|-------------------|
| EBT-SG1KT | FT15PXIII FT18PXIII FT20PXIII | 2018 ~ 2019 | 36 |
| EBT-SG2JT | FT20PXIII FT25PXIII | 2018 ~ 2019 | 17 |
| SG3BT | FT35PXIII | 2018 ~ 2019 | 2 |
| | | TOTAL | 55 |