

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2766	DATE	December 19 th , 2018
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	<p>The fault involves the plug connection from the wiring harness, which supplies power to the blower controller for the air conditioner. Due to inappropriate material of the plug connection coating, this may deteriorate due to friction corrosion caused by high current flow and vehicle vibration.</p> <p>This can lead to overheating of the plug connection and subsequently to melting. In very rare cases, this can lead to a fire.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-VA20	BMW 320i	2004 - 2010	37,706
LBA-PG20		2010 - 2011	6,294
LBA-PG20G		2010 - 2011	195
ABA-VR20	BMW 320i Touring	2006 - 2010	11,938
LBA-US20		2010 - 2011	3,490
ABA-WA20	BMW 320i Coupe	2007 - 2010	3,529
LBA-KD20		2010 - 2011	541
LBA-KD20G		2010 - 2011	76
ABA-VB23	BMW 323i	2005 - 2007	13,159
ABA-VB25	BMW 325i	2005 - 2010	6,715
LBA-PH25		2010 - 2011	1,199
ABA-VF25	BMW 325Xi	2007 - 2010	108
ABA-VS25	BMW 325i Touring	2005 - 2010	3,237
LBA-UT25		2010 - 2011	561
LBA-KE25	BMW 325i Coupe	2010 - 2011	277
ABA-VB30	BMW 330i	2004 - 2006	1,567
ABA-VD30	BMW 330Xi	2005 - 2007	153
ABA-PM35	BMW 335i	2006 - 2010	274
ABA-VB35		2010 - 2011	1,826
ABA-UV35	BMW 335i Touring	2006 - 2010	128
ABA-VS35		2010 - 2011	864
ABA-KG35	BMW 335i Coupe	2006 - 2010	237
ABA-WB35		2010 - 2011	2,113
ABA-DX35	BMW 335i Cabriolet	2006 - 2010	174
ABA-WL35		2010 - 2011	1,736
ABA-VA40	BMW M3 Sedan	2006 - 2010	502

CBA-VA40		2009 - 2011	131
ABA-WD40	BMW M3 Coupe	2007 - 2011	1,291
CBA-WD40		2010 - 2011	207
		TOTAL	100,228