

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-3765	Date	January 31, 2023
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	Due to a potentially wrong assembly of the heatshield of the brake booster, it's possible that the brake fluid reservoir can be damaged. The assembly of the heatshield may not be done properly. Due to the possible damage of the brake fluid reservoir by high temperatures in engine compartment at high engine load, it's possible that brake fluid can leak. If the brake fluid will get in touch with hot surfaces, it's possible that the brake fluid can ignite.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3BA-CDDNP	Golf GTI 2.0/180kW	2023	2
3BA-CDDNFF	Golf R 2.0/235kW	2023	7
3DA-CDDTT	Golf TDI/110kW	2023	3
		Total	12