

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	外-3766	DATE	31, Jan, 2024
MANUFACTURE	Tesla, Inc. (Japanese Importer; Tesla Motors Japan)		
DESCRIPTION OF DEFECT	In electric power steering, due to an inappropriate motor control program, the input current to the electric assist motor may become unstable and the assist force may change when the outside temperature is low. Therefore, irregular steering correction will be performed, and there is a risk that the steering device standards will not be met.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAA-3L13T	Model 3	2022	73
ZAA-3L23T			13
ZAA-3L23PT			3
ZAA-YL1YT	Model Y		1
		TOTAL	90