

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-3758	DATE	2024/2/8
MANUFACTURE	Mercedes-Benz AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	<p>On certain GLE (167 platform) vehicles, the left exterior reverse light might remain illuminated when the vehicle is not in the reverse position, contrary to the local requirements.</p> <p>Due to a malfunction which is caused by vibrations in the control unit of the left rear tail lamp, the left exterior reverse lamp could light up continuously.</p> <p>Other signal lights (right reversing light, brake light, direction indicator, etc.) are not affected by this issue.</p> <p>When engaging the reverse gear, both reversing lights would light up as intended. Thus, the associated possible change of the driving direction would be indicated and become apparent to the following traffic. It can be excluded that following traffic will be blinded by the permanent illumination of the left exterior reverse lamp.</p> <p>However, local legal requirements might not be met.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3DA-167119C	GLE300d 4MATIC	2019	215
3DA-167123	GLE400d 4MATIC		95
5AA-167159	GLE450 4MATIC		98
		TOTAL	408