

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	5431	DATE	January 9, 2024
MANUFACTURER	ISEKI & CO., LTD.		
DESCRIPTION OF DEFECT	In the vehicle control unit (ECU) of the agricultural tractor, due to improper control program of the ECU, communication error may occur when the ECU communicate with an implement through the Controller Area Network (CAN). Therefore, the vehicle cannot be controlled adequately, and in the worst case, one side of the wheels might remain braked when the vehicle starts, making it impossible to drive stably.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	BF60	2023	61
		2023	13
-	BF55	2023	11
		2023	5
-	BF50	2023	30
		2023	4
-	BF45	2023	23
		2023	2
-	BF35	2023	101
		2023	10
-	BF32	2023	37
-	BF29	2023	30
		2023	1
-	BF25	2023	39
		TOTAL	367