

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5430	DATE	January 18, 2024
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the electric power steering gear, due to an improper gear loading applied to gear engagement, the grease, which is applied to gear engagement, may be pushed out. Accordingly, the gear friction may increase, leading to an increased steering force.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
3CA-KH3R3P	Mazda 「CX-60」	2022-2023	12,440
3DA-KH3P		2022-2023	11,290
5BA-KH5P		2022-2023	5,233
5LA-KH5S3P		2022-2023	1,187
		Total	30,150