

第4号様式(英文リコール概要書) (第2関係)

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	5442	DATE	2024/1/23
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa city, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	Regarding some of hydraulic cylinder of cargo box of gull-wing truck, oil pressure go through from bottom side to rod side inside the cylinder because of inappropriate sealing structure of piston part. Therefore, the wing is not able to keep opening position and it comes down, and in the worst case, there is possibility that the operator will get injured during loading and unloading of the cargo.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QPG-CG5ZA	QUON	2016~2017	4
QPG-CG5ZE		2016	1
2PG-CG5CA		2018	2
TKG-FRR90S1	FORWARD	2016	1
TKG-FRR90S2		2016~2018	7
TKG-FRR90T2		2016~2017	6
SKG-FSR90S2		2017	1
SKG-FSR90T2		2017	1
SPG-FSR90T2		2016	1
LPG-FTR90S2		2018	1
2PG-FSR90T2		2018	1
2RG-FTR90V2		2018	1
QPG-FTR34T2		2017	2
TKG-FEB80		FUSO CANTER	2016
TKG-FK61F	FUSO FIGHTER	2016	1
TKG-FK64F		2016~2018	6
TKG-FK65FY		2017	1
TKG-FD7JMAA	HINO RANGER	2016~2017	4
TKG-FD9JLAA		2017	1
TKG-FD7JLAG		2016~2018	4
QKG-FE7JLAA		2017	1
QKG-FE7JMAG		2016	1
2KG-FD2ABG		2018	3
2PG-FD2ABA		2017	1
2PG-FD2ABG		2017~2018	2
QPG-FW1EXEJ	HINO PROFIA	2017	2
		TOTAL	57