

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5433	DATE	January 25,2024
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the internal motor of the EGR (exhaust gas recirculation system) valve, the frequency of operation exceeds the expected when driving on a congested road, etc., and the power distribution brush of the internal motor wears out prematurely, resulting in poor conduction, and the EGR valve may not operate. As a result of it, the engine warning light may come on and the emissions may not meet the regulatory values.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2012~2019	58,297
		TOTAL	58,297