

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	5445	DATE	Jan.31.2024
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the front lower arms of the front suspension, due to insufficient consideration for durability of usage environment, there is a possibility that the front lower arm(s) may have rust and cracks, when snow melting agents are frequently applied in snowfall area. If the vehicle is continuously operated in this condition, the cracks propagate, and in the worst case, the lower arm could separate and ball joint could drop off resulting in the vehicle becoming inoperative.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	NOTE
5BA-KSP210	[YARIS]	2019-2024	112,461	
5BA-MXPA10			77,240	
5BA-MXPA15			23,620	
6AA-MXPH10			156,624	
6AA-MXPH15			25,488	
6AA-MXPH14			656	
6AA-MXPH17			55	
6AA-MXPK10	[AQUA]	2021-2024	9,231	
6AA-MXPK11			105	
6AA-MXPK15			170,324	
6AA-MXPK16			2,264	
5BA-MXPC10G	[SIENTA]	2022-2024	1,118	
5BA-MXPC12G			26,057	
6AA-MXPL10G			3	
6AA-MXPL12G			40,069	
6AA-MXPL15G			1,637	
TOTAL			790,329	