

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	5449	DATE	20/2/2024
MANUFACTURE	VANTECH Inc. President and Representative Director Toru Sato		
DESCRIPTION OF DEFECT	The length adjuster of the rear-facing two-point seatbelt is installed inverted. If used as is, in the worst case scenario, the belt may not be restraining enough in the event of a rear-end collision.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
2DG-GDY231 改 2DG-GDY281 改 QDY-KDY231 改 LDF-KDY281 改 ABF-TRY230 改	CAMROAD	2019-2022	49 310 287 365 6
		TOTAL	1017