

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / ~~Import~~ Vehicles

CAMPAIGN No.	5454	DATE	February 22. 2024
MANUFACTURER	YANMAR AGRIBUSINESS CO.,LTD.		
DESCRIPTION OF DEFECT	<p>Regarding the running tension of agricultural combine harvester, due to insufficient evaluation at the design stage, the strength of the running tension spring and running tension arm bolt do not have enough strength. Therefore, if the vehicle is continued to be used in this state, high stress will be repeatedly applied to the vehicle, and in the worst case, there is a risk that the component will be damaged and the vehicle will no longer be able to travel.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
-	「YH6135」	2023	89	
	「YH7135」	2023	20	
		TOTAL	109	