

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2508	DATE	April 8,2010
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	IN THE VEHICLES EQUIPPED WITH THE OPTIONAL SRS SIDE & CURTAIN AIRBAG, THE BRACKET USED FOR INSTALLING THE CURTAIN AIRBAG TO THE VEHICLE BODY HAS NOT BEEN PROPERLY AFFIXED. DUE TO THIS CONDITION, IT IS POSSIBLE THAT THE SUBJECT AIRBAG WOULD NOT DEPLOY PROPERLY WHEN ACTIVATED.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GA3W	R V R	2010	12
		TOTAL	12