

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2 5 1 2	DATE	April.15.2010
MANUFACTURER	UD Trucks Corporation		
DESCRIPTION OF DEFECT	On Turbocharger of Heavy Duty CNG engines, Some of them might break because of insufficient intensity of the turbine blade. If it happens, then white smoke raises and not enough output power, then the vehicle might stop.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-CD45 series	—	1999	2
KL-CD48 series	—	2001~2007	24
KL-UA272 series	—	2004~2005	9
KL-UA452 series	—	2000~2007	116
		TOTAL	151