

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2517	DATE	Apr.22.2010
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	On certain heavy duty trailer tractors equipped with 16 speed transmission, the transmission contains the speed sensing rotor with insufficient hardness of the surface. This rotor would wear and allow the flange coupling bolts at the rear end of the transmission to be loosened causing the flange coupling together with propeller shaft comes off the vehicle if the worst comes.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-SH1FDGG	Hino Super Dolphin	2000～2003	152
KL-SS1FJGA		2000～2003	116
KS-SS1EKJA	Hino Profia	2004～2006	198
PK-SS1EKJA			
ADG-SS1EKXA		2006～2007	222
BDG-SS1EKXA			
		TOTAL	688