

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic / Import Vehicles)

CAMPAIGN No.	2518	DATE	April 22 , 2010
MANUFACTURER	Kobelco Construction Machinery Co., Ltd.		
DESCRIPTION OF DEFECT	<p>On travel unit, there are some cases that protectors don't add to the hoses due to inappropriate instructions of remedial repair, numbered "2101", dated on 18, April, 2008.</p> <p>Therefore, continuous operations without remedy may lead to hydraulic oil leaking and travel malfunction of the machine; where interference with the hoses and piping joints of swing unit can happen resulting in machine to shake in the worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
EDR-YE04	SK125W	2006 ~ 2008	119
TOTAL			119