

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2525	DATE	April 22, 2010
MANUFACTURE	TADANO LTD.		
DESCRIPTION OF DEFECT	Due to inadequacy of the exhaust pipe flange weld, there are cases where cracking in the flange weld may develop from stress of engine vibration which, in worst case scenario, can cause the exhaust pipe to breaking away at the flange and lead to excessive exhaust noise emission.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
JDS-T003	TADANO, GR-250N-2	2008 - 2010	538
		TOTAL	538