

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

| | | | |
|-----------------------|---|------|----------------|
| CAMPAIGN No. | 2526 | DATE | April 26, 2010 |
| MANUFACTURE | TOYOTA INDUSTRIES CORPORATION | | |
| DESCRIPTION OF DEFECT | In some of the LPG fuel fork lift vehicles, there is a possibility that wrinkles may occur at the bending portion of the LPG pipe, because the bending work process is not adequate. If the vehicles have been kept using with this condition, the vibrations may damage the LPG pipe, and then it may cause LPG leak. In the worst case, it may result in fire on the vehicle. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|--------|-----------------|---------------------|-------------------|
| 8FG18 | TOYOTA GENE0 | 2006 - 2007 | 40 |
| 8FG25 | | 2006 - 2007 | 19 |
| 8FGK30 | | 2006 | 1 |
| 8FGJ35 | | 2006 - 2007 | 15 |
| | | TOTAL | 75 |