

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2534	DATE	May 20,2010
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	<p>IN THE VEHICLE FOR DISABLED PEOPLE IN WHICH THE HYDRAULIC LIFT FOR THE WHEEL CHAIR IS INSTALLED, FOREIGN MATERIAL SUCH AS DUST ETC. MAY BE ATTACHED TO THE AREA AROUND THE SWITCH DUE TO INSUFFICIENT DUST PREVENTION ABILITY IN THE SWITCH TO DETECT THE LOCATION OF THE HEIGHT OF THE VEHICLE FLOOR. AND THE RETURN HOSE BY WHICH OOZED OIL FROM THE HYDRAULIC CYLINDER IS RETURNED TO THE RESERVOIR TANK MAY BE DAMAGED BY THE REPETITIVE BENDING WHEN THE LIFT IS USED CAUSING OIL LEAK ONTO THE SWITCH RESULTING IN THE OPERATION FAILURE DUE TO THE JAMING OF THE FOREIGN MATERIAL SUCH AS DUST ETC. IN THE SWITCH. AS A RESULT, IT MAY BE POSSIBLE THAT THE WHEEL CHAIR IS TIPPED OVER THE INTERIOR OF THE VEHICLE DUE TO THE FAILURE OF THE FUNCTION TO AUTOMATICALLY STOP THE LIFT AT THE LEVEL OF THE FLOOR OF THE VEHICLE.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LE-U61V(改)	MINICAB	2004	35
LE-U62V(改)		2004	36
TA-U61W(改)	TOWNBOX	2004	18
TA-U62W(改)		2004	24
LE-U71V(改)	CLIPPER	2004	20
LE-U72V(改)		2004	16
		TOTAL	149