

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN NO.	2535	DATE	May 25 ,2010
MANUFACTURER		ISUZU MOTORS LIMITED	
DESCRIPTION OF DEFECT		<p>In the engines of the refrigerator vehicles, the installation strength of the bracket for the idle pulley for the refrigerator compressor driving belt is so insufficient that a mating face of the idle pulley bracket and the refrigerator compressor bracket will be abraded due to belt tensile force, compressor driving force, etc. Thus, if they are used as are, the brakcet mounting bolts will be broken, and in the worst case, the pulley and the bracket may come off and obstruct other traffic.</p>	

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PJ-CVR77K6	GIGA	2005	1
PJ-CVR77N6		2005	1
PJ-CVR77P6		2005-2006	3
PDG-CVR77P8		2009	1
PJ-CXE77X6		2006	8
PKG-CXE77X8 PDG-CXE77X8		2007-2009	12
PJ-CXG77X6		2006-2007	4
PKG-CXG77X8		2008	1
PJ-CXY77Q6J		2006	1
PKG-CXY77Q8J PDG-CXY77Q8J		2007-2009	4
PJ-CXY77S6J		2006	1
PDG-CXY77S8J		2007	3
PJ-CXY77V6J		2006	3
PKG-CXY77V8J PDG-CXY77V8J		2007-2009	4
PJ-CYE77Y6		2007	6
PJ-CYE77Y6Z		2006	1
PDG-CYE77Y8Z		2008	2
PJ-CYJ77W6 PJ-CYJ77W6A		2005-2007	52
ADG-CYJ77W7		2006-2007	3

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
PKG-CYJ77W8 PKG-CYJ77W8A PDG-CYJ77W8 PDG-CYJ77W8A	GIGA	2007-2010	272	
PDG-CYJ77W8L		2007-2009	5	
PKG-CYJ77W8Z PDG-CYJ77W8Z		2007-2009	10	
PJ-CYL77Q6		2006	1	
PDG-CYL77Q8		2007-2009	2	
PDG-CYL77R8		2007-2008	3	
PJ-CYL77T6		2005-2006	3	
PJ-CYL77V6 PJ-CYL77V6A		2005-2007	85	
PJ-CYL77V6Z		2006-2007	5	
ADG-CYL77V7 ADG-CYL77V7A		2006-2007	7	
PKG-CYL77V8 PKG-CYL77V8A PDG-CYL77V8 PDG-CYL77V8A		2007-2010	364	
PKG-CYL77V8Z PDG-CYL77V8Z		2007-2009	29	
PDG-CYM77V8		2007	1	
PDG-CYY77Q8J		2007	1	
PKG-CYY77S8J PDG-CYY77S8J		2007-2008	2	
PJ-CYY77V6		2006-2007	6	
PJ-CYY77V6J		2006-2007	10	
PKG-CYY77V8 PDG-CYY77V8		2007-2009	13	
PKG-CYY77V8J PDG-CYY77V8J		2007-2009	32	
PKG-CYY77V8Z PDG-CYY77V8Z		2009	9	
			TOTAL	971