VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

| | _ |
|------------------|----------|
| Domestic (Import | Vehicles |
| | |

| CAMPAIGN No. | GAI-1670 | DATE | May 31, 2010 |
|-----------------------|---|------|--------------|
| MANUFACTURE | Automobiles PEUGEOT, Automobiles CITROEN | | |
| | (Japanese Importer : Peugeot Citroen JAPON) | | |
| DESCRIPTION OF DEFECT | On the vehicles concerned. An electrical contact of the brake switch may not be in conformity as such the computers of the vehicle may not detect brake pedal depression. This may result malfunction of the brake lamps, prevent the shift lever from being released from the parking position, and cause difficulty in starting the engine. The campaign consists of replacing the brake switch and modifying its electrical supply by adding a strap to the harness. | | |
| | | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|---|--------------------------|------------------------|----------------------|
| ABA-D2BRV ABA-D2BRY ABA-D2V ABA-D2Y GH-D2 GH-D2BR GH-D2BRV GH-D2BRY GH-D2BRY GH-D2V GH-D2V GH-D2Y ABA-D2CPV | Peugeot 407 | 2004 – 2010 | 4836 |
| ABA-X3RFJ ABA-X3XFU ABA-X7RFJ ABA-X7XFV GH-X3RFJ GH-X3XFU ABA-X6XFV | Citroen C5 Citroen C6 | 2004 - 2009 | 1950 |
| | | TOTAL | 6786 |