

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-1674	DATE	Jun 4, 2010
MANUFACTURER	ALPINA Burkard Bovensiepen GmbH+Co. (Japanese Importer: Nicole Racing Japan Co. Ltd)		
DESCRIPTION OF DEFECT	Due to inappropriate material of the check valve attached to brake booster vacuum line, seal-up effect may not be sufficient and engine oil mist may enter the brake booster, which may cause damage of inner diaphragm. Then brake booster air tightness may not be maintained and in worst case braking distance may be longer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GH-MH10	ALPINA B7	2004 - 2006	20
ABA-MH10	ALPINA B7	2008	1
GH-TH10	ALPINA B7	2005 - 2006	14
ABA-TH10	ALPINA B7	2006 - 2008	5
GH-NH10	ALPINA B7 Long	2004 - 2006	34
ABA-NH10	ALPINA B7 Long	2007 - 2008	5
ABA-VH12	ALPINA B6 Coupe	2006 - 2007	29
ABA-WH12	ALPINA B6 Cabrio	2006 - 2007	11
ABA-6H1S	B6 S Coupe	2008 - 2009	10
	B6 S Cabrio	2008 - 2009	3
ABA-RH12	ALPINA B5	2005 - 2007	128
ABA-SH12	ALPINA B5 Touring	2007	4
ABA-XH12	B5 S	2008 - 2010	31
ABA-YH12	B5 S Touring	2008 - 2009	2
		TOTAL	297