

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2 5 4 8	DATE	J u n . 1 1 . 2 0 1 0
MANUFACTURER	HANTA MACHINERY CO., LTD.		
DESCRIPTION OF DEFECT	<p>DUE TO INADEQUATE FIXING ON HYDRAULIC HOSES CONNECTING TO HYDRAULIC MOTOR FOR DRIVING FRONT WHEEL, HYDRAULIC HOSES MAY BE WORN OUT BY RUBBING AGAINST FRONT WHEEL.</p> <p>ACCORDINGLY HYDRAULIC OIL MAY LEAK FROM DAMAGED HYDRAULIC HOSES.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KDN- F 4 5 W 3	F 4 5 W 3	2 0 0 9	4 5
KDN- A 4 5 W 3 B			
		TOTAL	4 5