

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2561	DATE	JUN. 15 2010
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some heavy-duty trucks, if the periodical replacement of the fuel filter and the periodical cleaning of the fuel tank have not conducted correctly, impurities mixed in the fuel may cause wear of the injector seats. This increases the fuel injection amount and raises the exhaust temperature. Then high exhaust temperature may cause cracks at the right rear of the exhaust manifold, and the exhaust gas leaked from these cracks may burn the resin rear cover.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
KL-FV50LHR	FUSO	2000~2007	723
		TOTAL	723