VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2558	DATE	June 17 2010		
MANUFACTURER	KATO WORKS CO.,LTD.				
DESCRIPTION OF DEFECT	The accelerator of the crane carrier is equipped with only one return spring. This does not satisfy the safety standard of the road transport vehicle.				

TYPE	COMMERCIAL	MODEL YEAR		NUMBER OF
	NAME	RE	CALLED	VEHICLE
KA5153	-	2007 ~ 2010		33
KA6350	-	2007 ~ 2010		20
			TOTAL	53