

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN NO.	2 5 4 6	DATA	June.18.2010
MANUFACTURER	Kaihatsu Kouken Co.,Ltd.		
DESCRIPTION OF DEFECT	<p>For lack of lubrication of the joints for hydraulic pump axis Rotary Snowplow power transmission equipment (gearbox) in during use, wear the joints have to be. Therefore, you might can no longer be driving and continue to use in its entirety, for hydraulic pump axial joints is worn away.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
K R 1 0 A	H K 1 5 2 K	2 0 0 8 ~ 2 0 0 9 R2-01115 ~ R2-01118	4
TOTAL			4