

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2 5 6 6	DATE	Jun.30.2010
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>Since the assmby process of the seat belt buckle in the front seat is inappropriate, the component part inside the buckle may have been broken. Due to this condition, If the broken piece of the part is stuck in the buckle, the seat belt could not be fastened.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DBA-AK12	MARCH	2 0 1 0	3,626
DBA-BNK12		~	313
DBA-YK12		2 0 1 0	79
		(Service Part)	2
		TOTAL	4, 0 2 0