

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2570	DATE	Jul.5.2010
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the valve operating system of the engine, due to inclusion of micro-foreign objects in the material of the valve spring, there is a possibility that the strength of the valve spring may degrade, causing the spring to break. If the spring(s) in the engine breaks, abnormal noise and rough engine performance will be noticed. In the worst case, the engine could stop suddenly while the vehicle is in motion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRS184	CROWN	2005-2008	20,510
DBA-GRS204		2007-2008	7,188
DAA-GWS204		2008	2,047
DBA-GRS191	GS350	2005-2008	14,004
DBA-GRS196		2005-2008	1,600
DAA-GWS191	GS450h	2006-2008	3,957
DBA-URS190	GS460	2007-2008	634
DBA-GSE21	IS350	2005-2008	2,887
		2005-2008	2,666

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-USF40	LS460	2006-2008	27,585
DAA-UVF45	LS600h	2007-2008	5,217
DAA-UVF46	LS600hL	2007-2008	3,608
		TOTAL	91,903