

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	2573	DATE	July 20, 2010
MANUFACTURE	Aichi Corporation		
DESCRIPTION OF DEFECT	The electric wires, which control the lighting and engine, may be damaged due to the possible contact between electric wires and hydraulic hoses. In result, lighting or/ and engine may cease.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
BDG-NKS85AN BKG-NKR85AN BKG-NHR85AN	ELF (ISUZU)	2007-2010	215
BDG-LKS85AN BKG-LKR85AN	TITAN (MAZDA)	2007-2009	10
		TOTAL	225