

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

**Import Vehicle**

|                              |  |             |                       |
|------------------------------|--|-------------|-----------------------|
| <b>CAMPAIGN No.</b>          | <b>1 6 8 8</b>   | <b>DATE</b> | <b>July 22 , 2010</b> |
| <b>MANUFACTURER</b>          | <b>Manitowoc Crane Group Germany GmbH</b>  |             |                       |
| <b>DESCRIPTION OF DEFECT</b> | <b>In the accelerator system of the crane's carrier vehicle, the accelerator pedal is equipped with only one return spring and thus does not conform to the rules in the Security Standards for Road Transport Vehicles.</b> |             |                       |

| <b>TYPE</b> | <b>COMMERCIAL NAME</b> | <b>MODEL YEAR RECALLED</b> | <b>NUMBER OF VEHICLE</b> |
|-------------|------------------------|----------------------------|--------------------------|
|             | <b>KMG6300</b>         | <b>2 0 0 5 - 2 0 0 7</b>   | <b>5</b>                 |
|             | <b>KMG5220</b>         | <b>2 0 0 7 - 2 0 0 8</b>   | <b>5</b>                 |
|             | <b>KMG5130</b>         | <b>2 0 0 6 - 2 0 0 8</b>   | <b>1 6</b>               |
|             |                        | <b>TOTAL</b>               | <b>2 6</b>               |