

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2583	DATE	July 29, 2010
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	On 3-speed automatic transmission vehicles which are often used at a high speed such as ones for commercial purpose and if they are driven with insufficient engine oil, it is possible the connecting rod metal may get seized and abnormal noise may emanate. Accordingly, if such vehicles keep running at a high speed, the engine may be broken and possibly lead to a loss of drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBD-S321V	HIJET	2007-2010	68,753
GBD-S321V			
EBD-S331V			
GBD-S331V			
EBD-S321W	HIJET DECKVAN		1,658
EBD-S331W			
		TOTAL	70,411