

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	2579	DATE	Jul . 29 , 2010
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	On certain transfer case of manual transmission, oil lubrication hole had not been processed as the production processing program was inappropriate. If the vehicle was used continuously under this condition, gears may be broken due to improper oil lubrication and lead to incapable driving in the worst case.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BM9	Legacy	2010	38
DBA-BR9		2010	59
		TOTAL	97