

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

CAMPAIGN No.	2582	DATE	August 3, 2010
MANUFACTURER	NIPPON TREX CO., LTD.		
DESCRIPTION OF DEFECT	The axles used for semi-trailers do not have enough room of strength for the various use situation. This condition might cause crack by long-term use to the spindle of the axle. Therefore, as a result, the axle might be broken in occasion.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PFB24101	—	1994~1995	316
P326SA	—	1994	2
P328SA	—	1994	1
P339SE	—	1995	1
P339VB	—	1994	1
P339ZR	—	1994	1
P339ZZ	—	1994	2
PFB328AA	—	1994	3
PFB333AA	—	1994	2
PFB336AA	—	1994	1
PFB342AA	—	1994	5
PFC241AD	—	1994	1
PFC241AE	—	1994	1
PFF241AA	—	1994	1
PFF241AE	—	1994	1
PFF241AF	—	1994	1
PFF241AH	—	1994	1
PFF331AA	—	1995	1
PFF341AB	—	1994	1
PFG241AC	—	1994	1
PFG241AH	—	1994	2
PFG241AJ	—	1994	1
PFG241AR	—	1994	1
PFG241AU	—	1994	3
PFG241AZ	—	1994	1
PFG342AE	—	1995	2
PFS241AB	—	1994	1
PFW241AD	—	1994	1
PFW241AE	—	1994	2
PFW241AK	—	1994	1

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PFW241BZ	—	1994	1
PFW241CA	—	1994	1
PLB241AA	—	1994	2
PLH241AA	—	1994	6
VFB24101	—	1994～1995	3
VFR241AD	—	1994	1
VPD241AB	—	1994	1
VPD241AE	—	1994	1
		TOTAL	375