

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2591	DATE	September 3. 2010	
MANUFACTURER	Komatsu Utility Co. , Ltd.			
DESCRIPTION OF DEFECT	Due to poor sealing performance of check valve, which is installed to master cylinder of disk brake truck, brake pressure might be dropped down because of oil leak and the braking stop distance will be longer in the worst case.			
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	
M025A	-	2000~2001	4	
M187	-	2003	1	
SB-M187	-	2005	1	
SB-M187T	-	2006~2008	4	
		TOTAL	10	