VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	2 5 9 3	DATE	September 10, 2010			
MANUFACTURER	SAKAI HEAVY INDUSTRIES, LTD.					
DESCRIPTION OF DEFECT	Because the strength of locknut of a nut fixing bearing in the hydraulic motor with gearbox is poor, there is the case that the nut loosens. By the continuation of use, abnormal noise occurs from the gearbox, and the hydraulic motor with gearbox may be damaged in the worst.					

ТҮРЕ	COMMERCIAL NAME	MODEL YEAR RECALLED		NUMBER OF VEHICLE
KDN-1R5	R 2 – 2	20	08-2009	29
			TOTAL	29