

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	2607	DATE	Sept.17 2010
MANUFACTURER	YOKOHAMA SHARYO KOGYO CO.,LTD.		
DESCRIPTION OF DEFECT	There is a fear to happen that reinforced cross member and V-rod will be damaged because there is a case which will not have enough gap between reinforced cross member and V-rod at the rear part of the spacer when remodeling to raise the height of spacer for fifth wheel coupling of the tractor, and if V-rod will move during the running and then if it will project upper than the surface of frame, there is a possibility it will be interfered with the reinforced cross member of rear part of spacer.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
PKG-EXD52E8	GIGA	2007 ~ 2010	15
TOTAL			15